# EO 30-001 Relocation of Wiper Switch

**Effectivity:**

EC135 T3H/P3H

**Description of modification:**

With this modification, the wiper switch on the PIC collective lever is relocated as shown in Fig. 1. This reduces the risk of an unintended activation of the windscreen wiper when the collective lever is fixed with its locking lug, as unintended activation in dry conditions causes scratches in the windscreen. The actual function and activation of the wiper is not changed. Pushing the 4-way toggle switch once in any position/direction causes one cycle of the windscreen wiper. The new switch is labelled for its intended function.





Fig. 1 – Relocation of wiper switch on PIC Collective Lever

**Ordering information:**

There are no additional parts needed, the rewiring is accomplished according to a Wiring Diagram.

For order placement, please contact our customer service department “csc@heliair.eu” or for technical questions contact our engineering department “engineering@heliair.eu”.

**Approval:** EASA Minor Change 10068469